









# ASSEMBLE INSTRUCTION


T-5015C



①



②










# ASSEMBLE INSTRUCTION


T-5015E



①





②





# ASSEMBLE INSTRUCTION


T-5015S




①



1x




2x




M8

4x



4x



M5

1x

②

