









ASSEMBLE INSTRUCTION


T-5016C



①



②





ASSEMBLE INSTRUCTION


T-5016E



①




1



1x

2



2x

A



M8

8x

B



8x


C



M5



1x

②









ASSEMBLE INSTRUCTION

T-5016S



①



②

